

Vehicle Inspection Report

Vehicle

**Make** TOYOTA  
**Model** AYGO X VVT-I - 998cc  
**Date Inspected:** 22/07/2024 12:53

**Reg** LR20ZPJ  
**Agree No**  
**VIN** JTDKGN70N535981



Vehicle Details

**Engine Size** 998cc cc    **Body Type** Hatchback    **Mileage** 12,505 miles  
**Doors** 5    **Colour** Red    **Fuel** Petrol  
**Fuel Level** Red    **Trans** Manual    **Gears** 5  
**DFR**    **YOM**    **Non-run** No  
**Taxi** No    **Ser Dam** No    **Police** No  
**MOT Location** T/A    **MOT Expiry** 18/05/2025

Miscellaneous

**No. Keys** 2  
**Master Key** Yes  
**Spare Key** Yes

Tyres & Wheels

**O/S Front** 3 Continental    **Spare Wheel** Yes  
**O/S Rear** 5 Continental    **Wheel Size** 14"  
**N/S Front** 3 Continental    **Locking Wheel Nut** No  
**N/S Rear** 5 Other    **Alloys** No

Interior Condition

**Carpets** Average  
**Upholstery** Average  
**Seats** Average  
**Parcel Shelf** Yes

Extras

<b>Metallic Paint</b>	No	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	No	<b>Sun Roof</b>	No	<b>Elec Windows</b>	2	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	4	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	No	<b>Drv Airbag</b>	Yes	<b>Pass Airbag</b>	Yes	<b>Reversing Camera</b>	No
<b>EML</b>	No	<b>Adaptations</b>	No				